IDEA-1637-63 Copy S of //

1963

MEMORANDUM FOR : Chief, IDEALIST, CSA

SUEJECT : U-2 Escape System

1. Review of LAC ejection sest test reports SP
384 and SP 391 and meetings with LAC engineers,
personnel and several detechment commanders reveals the
following:

25X1A

- a. The primary method of escape is to eject through the canopy.
- The secondary method is to samually release the canopy and then eject.
- c. In case of ejection seat failure the last elternative is to manually release the canopy and go over the side with the 40+1b. survival kit attached to the man's persebute harness.
- O. Per LAC test results in their report SP
 191 the forces exerted on the knees when
 contact is made with plexiglass parts of
 the canopy not removed by the extended
 necdrest can be as high as \$50 lbs. on one
 tage. This situation compromises successful
 ejection without injury.
- oulling back a bandle on each side of the cocapit at approximately the same time. Since the right side handle is used frequently for ground eggress the pull force is less than the left side handle which is selden used. This introduces the possibility in an emergency of the pilot releasing the right side first allowing windblest to get under the canopy before the left side is released which could result in the canopy handles up thereby making successful ejection virtually impossible.

IDEA-1637-63

2. Recommendations:

- s. LAC should provide means of forcibly ejecting the canopy as the first step in the primary ejection sequence. It is believed this could be done with explosive bolts.
- b. Equal pull force should be assured for both the right and left hand manual release handles to insure a positive canopy separation if the manual method is employed.

25X1A

Aircraft Systems Division (Special Activities)

25X1A

ASD/OSA

(23 December 1963)

Distribution:

Cy 1 - C/IDEA/GSA

2 - AD/GSA

3 - DAD/OBA

4 - D/TECH/OSA

5 - D/PA/OSA

6 - 35/05A

7 - MD/GSA

6 - INTEL/OSA

9 - ASD/OSA

10 - chrono

11 - BB/OSA